REMEDIAL WORKS NOTIFICATION



DESCRIPTION OF MINO	R WORKS			
1. Description	n of the remedial works			
All C2 remedial actions completed following 5 year inspection and testing (LTE-001260). Please retain				
this document alongside test certificate to show a 'Satisfactory' status.				
2. Location/Address				
The Oldway Centre	2			
Stryd Fawr				
Swansea	Swansea			
SA1 1LA				
3. Date minor work	ks completed	02/04/2024		
4. Details of departures, if any, from BS 7671:2018				
No C3 observations completed.				
COMMENTS				
DB Appartment 63 - faulty MCB replaced with new				
All missing MCB blanks replaced with new to ensure correct IP ratings at DBs.				
DB level 1 - Loose connections reterminated and thermally damaged breakers replaced with new				
All damaged accessories replaced with new to ensure no access to live parts. DB 134 - Socket behind sink blanked off and linked out as within 300mm.				
DB Laundry - all poor terminations re-terminated to ensure no excess copper. DB Managers - RCBO fitted to ensure disconnection times, tested 24.6ms, test button ok.				
Grommets and fire barriers reinstated throughout site where required.				
Faulty PIR replaced with new.				
PART 3. DECLARATION				
I/We certify that the said works do not impair the safety of the existing installation, that the said				
works have been designed, constructed, inspected and tested in the accordance with BS 7671:2018				
(IET Wiring Regulations) amended to N/A and that the said				
works to the best of My/Our knowledge and belief, at the time of My/Our inspection, the work				
complied with BS 7671:2018				
Name	Bryn Howard	Signature		
			Blm/	
For and on behalf of	Salvus Total Solutions Ltd			
		Position	Qualified Supervisor	
Address	8a The Courtyard, Mulberry G	Green		
	Old Harlow, Essex, CM17 0ET	Date	07/06/2024	
	· · · · ·			
Registration No.	600246000			