

## Radon Test Results Hockett Gulch Apartments Building 1

Serial Number	Start Date	Start Time	Stop Date	Stop Time	Temp °F	Room	Test Result		Floor	Unit	OK or FIX	Comments
Building 1												
20726470	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	1.9 pCi/L		1	1102	OK	
20726473	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.7 pCi/L		1	1104	OK	
20726469	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	1.1 pCi/L		1	1101	OK	
20726468	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.7 pCi/L		1	1103	OK	
20726467	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.3 pCi/L		2	1202	OK	
20726466	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.5 pCi/L		1	1116	OK	
20726465	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.7 pCi/L		1	1113	OK	
20726463	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.3 pCi/L		2	1206	OK	
20726462	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.3 pCi/L		1	1109	OK	
20726461	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.7 pCi/L		1	1110	OK	
20726459	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.3 pCi/L		2	1208	OK	
20726460	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.9 pCi/L		1	1105	OK	
20726458	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	1 pCi/L		1	1114	OK	
20726456	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.7 pCi/L		1	1115	OK	
20726457	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.6 pCi/L		1	1112	OK	
20726455	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.8 pCi/L		1	1106	OK	
20726416	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.6 pCi/L		1	1107	OK	
20726417	06/06/2024	5:00PM	9:00AM	6/13/2024		KITCHEN	0.9 pCi/L		1	1111	OK	